



**FEDERATION FRANÇAISE DE
PARACHUTISME**

62 rue de Fécamp - 75012 PARIS
Tél : 01.53.46.68.68 - Fax : 01.53.46.68.70

e-mail : ffp@ffp.asso.fr

Web : www.ffp.asso.fr

CONSEIL SECURITE
CIRCULAIRE DE SECURITE N° 185

Réf.: 11/1173

Date: 5 Octobre 2011

Emetteur: F.F.P.

Objet: Rappel pour échange de certains sectionneurs et contrôle de certains autres des appareils VIGIL.

Matériels concernés: VIGIL dotés de sectionneurs datés d'Octobre 2007
VIGIL dotés de sectionneurs datés d'avant Juin 2008

Texte: Suite à un incident survenu au Canada, il a été découvert un sectionneur, qui bien qu'activé, n'a pas sectionné la bouclette de verrouillage. La raison en était l'**absence de la partie couteau** à l'intérieur du sectionneur en cause.

Actions: Application des recommandations précisées dans le Bulletin de Service du constructeur (ci-joint).

Dépose et renvoi immédiat au constructeur de tous les sectionneurs datés 10/07.
Contrôle sur site de tous les sectionneurs datés d'avant Juin 2008 (hormis ceux concernés par l'alinéa précédent).

Application à caractère **IMMEDIAT** et **OBLIATOIRE** avant le prochain saut.

Personnel qualifié: Plieurs

Date d'application: avant le prochain saut du matériel.

Diffusion: Tous publics.

AFFICHAGE OBLIGATOIRE



AAD sa/nv
Bld A.Reyers, 193
1030 Brussels – Belgium – Europe
+32 2 732 65 52 – Fax : +32 2 736 06 27
www.vigil.aero - info@vigil.aero

EMERGENCY PRODUCT SERVICE BULLETIN
(Supersedes Product Service Bulletin PSB-6)

Issue Date : **October 4, 2011**

Bulletin Number : **PSB-7**

Subject : **Vigil Cutters**

Compliance : **Mandatory**

Identification:

Vigil AAD, All Cutters produced in October 2007
Part Number: 9582006
Date of Manufacture: 10-07 (**mm-yy**)
(See Photo 1.)

Background:

The following incident occurred on the 14th September 2011 at the Saint-Jean Chrysostome (Canada) drop zone:

A skydiver failed to deploy his main canopy and manually pulled his reserve handle with insufficient altitude to fully deploy the reserve canopy. During the investigation of the incident it was discovered that the loop was neither cut nor trapped by the cutter.

Compliance:

In the preliminary report prepared by the Royal Military Academy, it was stated that the knife blade was missing. (See the separate Royal Military Academy report.)

Vigil R&D has confirmed that the electronics worked correctly and fired the cutter, but because of the absence of the knife blade, the closing loop could not be cut. **This cutter was part of a production batch of 299 pieces, produced in October 2007. (See Photo 1.)**

A person other than the usual person at the relevant cutter assembly post was working at the post at the time during which the October 2007 batch was manufactured. The cutter manufacturer has confirmed that the failure to install the knife blade was caused by error during the cutter assembly process.

This appears to be an isolated case. We are not aware of any similar assembly failure in any of the cutters which the cutter manufacturer has produced for any of their customers, including NASA and the US Armed Forces.

A group of 15 cutters from that batch have been activated by the Royal Military Academy for test purposes, and all worked to according to specifications. (See the separate Royal Military Academy report.)

In the interest of safety, AAD has decided to recall all cutters from this October 2007 cutter batch and to replace all those cutters free of charge. The removed cutter must be returned to AAD sa/nv or Vigil USA, LLC once the replacement cutter has been received. (Please contact AAD sa/nv or Vigil USA, LLC for return information and instructions.) This will enable us to personally examine and analyze as many cutters as possible from this batch in order to verify that this, in fact, has been an isolated incident.

In the interest of additional safety, we have devised a field test, which can be performed on any Vigil cutter, using a magnet to confirm the presence or lack of a knife blade. It can be done using any magnet on any cutter. Either a small (see Photo 2A) or a larger (see Photo 2B) magnet may be used. If there is a knife blade present, the magnet will be attracted to the knife blade.

Note: All Cutters manufactured from June 2008 have been x-rayed as part of our quality control process, and we have confirmed that the knife blade is present.

Compliance Date:

Because of the seriousness of this matter, this Emergency Product Service Bulletin must be complied with before the next jump on all Vigils with the following serial numbers (See List A below, which identifies the affected Vigils by the original gold Q.C. hologram numbers.) **Please note that this list is not exhaustive since some cutters may have been removed from the original Vigil for which they were provided and may have been used, without our knowledge, as replacements on other Vigils.** Some cutters may have a silver hologram because they

were issued from stock or as replacements via our dealers. Therefore, verification of the Date of Manufacture ("DOM") of the cutter must be performed at the time of the next reserve repack. **Every cutter found with a DOM of 10-07 (see Photo 1) must be replaced before the next jump, and the cutter which was removed must be returned to Vigil.** (Please contact AAD sa/nv or Vigil USA, LLC for return information and instructions.)

For additional safety, we highly recommend that the magnet test be performed on each cutter manufactured prior to June 2008.



Photo 1



2A



2B

Photo 2
Magnet Test Procedure

List A: Serial numbers of Vigils with cutters manufactured in 10/07

Device #	QC n°	Device #	QC n°	Device #	QC n°	Device #	QC n°	Device #	QC n°	Device #	QC n°
6239	H320	9269	L062	9352	L144	9445	L201	9513	L296	11261	M664
7671	I855	9270	L063	9353	L145	9446	L202	9514	L297	11263	M665
9207	L000	9272	L064	9354	L146	9447	L203	9515	L298	11264	M666
9208	L001	9274	L066	9355	L147	9369	L214	9516	L299	11265	M667
9209	L002	9275	L067	9363	L154	9393	L215	9517	L300	11267	M668
9210	L003	9276	L068	9365	L155	9396	L216	9518	L301	11268	M669
9211	L004	9277	L069	9366	L156	9397	L217	9519	L302	11269	M670
9220	L010	9309	L099	9367	L157	9401	L218	9520	L303	11271	M672
9221	L011	9310	L100	9370	L158	9402	L219	9521	L304	11272	M673
9223	L012	9311	L101	9371	L159	9403	L220	9522	L305	11273	M674
9224	L013	9312	L102	9373	L160	9404	L221	9523	L306	11274	M675
9226	L014	9313	L103	9374	L161	9405	L222	9524	L307	11276	M676
9227	L015	9314	L104	9375	L162	9406	L223	9525	L308	11277	M677
9229	L016	9316	L105	9376	L163	9410	L224	9526	L309	11278	M678
9230	L017	9317	L106	9377	L164	9411	L225	9527	L310	11280	M679
9231	L018	9318	L107	9378	L165	9412	L226	9528	L311	11281	M680
9232	L019	9202	L108	9379	L166	9413	L227	9546	L329	11282	M681
9233	L020	9299	L109	9380	L167	9414	L228	9549	L332	11283	M682
9236	L021	9301	L110	9381	L168	9416	L230	9550	L333	11285	M683
9238	L022	9315	L111	9382	L169	9478	L264	9551	L334	11286	M684
9241	L023	9319	L112	9383	L170	9479	L265	9552	L335	12518	N725
9242	L024	9320	L113	9385	L171	9480	L266	9553	L336	12556	N750
9192	L025	9321	L114	9386	L172	9481	L267	9554	L337	22756	X201
9196	L026	9322	L115	9388	L173	9482	L268	9555	L338	22765	X210
9194	L027	9323	L116	9389	L174	9483	L269	9556	L339	22766	X211
9235	L036	9324	L117	9390	L175	9484	L270	9557	L340	22767	X212
9239	L037	9325	L118	9420	L176	9485	L271	9558	L341		
9240	L038	9326	L119	9421	L177	9487	L272	9559	L342		
9243	L039	9327	L120	9422	L178	9489	L273	9560	L343		
9244	L040	9328	L121	9423	L179	9490	L274	9561	L344		
9245	L041	9330	L122	9424	L180	9491	L275	9563	L345		
9246	L042	9331	L123	9425	L181	9492	L276	9564	L346		
9247	L043	9332	L124	9426	L182	9493	L277	9565	L347		
9248	L044	9333	L125	9427	L183	9494	L278	9566	L348		
9249	L045	9334	L126	9428	L184	9495	L279	9567	L349		
9250	L046	9335	L127	9429	L185	9496	L280	9568	L350		
9251	L047	9336	L128	9430	L186	9497	L281	8186	L361		
9252	L048	9338	L130	9431	L187	9498	L282	9612	L362		
9254	L049	9339	L131	9432	L188	9499	L283	9633	L406		
9256	L050	9340	L132	9433	L189	9500	L284	10702	M240		
9257	L051	9341	L133	9434	L190	9502	L285	10703	M241		
9258	L052	9342	L134	9435	L191	9503	L286	11249	M654		
9259	L053	9343	L135	9436	L192	9504	L287	11250	M655		
9260	L054	9344	L136	9437	L193	9505	L288	11251	M656		
9261	L055	9345	L137	9438	L194	9506	L289	11252	M657		
9262	L056	9346	L138	9439	L195	9507	L290	11253	M658		
9263	L057	9347	L139	9440	L196	9508	L291	11254	M659		
9264	L058	9348	L140	9441	L197	9509	L292	11257	M660		
9266	L059	9349	L141	9442	L198	9510	L293	11258	M661		
9267	L060	9350	L142	9443	L199	9511	L294	11259	M662		
9268	L061	9351	L143	9444	L200	9512	L295	11260	M663		

Authority:

Yann Bronnec
P.R. Manager

Edwin Bollaerts
Office Manager

Jo Smolders
Managing Director

AAD sa/nv

Bld A.Reyers, 193
1030 Brussels – Belgium – Europe
+32 2 732 65 52 – Fax : +32 2 736 06 27
www.vigil.aero - yann@vigil.aero - info@vigil.aero

Vigil USA LLC

1645 Lexington Avenue
Deland, FL 32724
+386 736 8464 – Fax : +386 736 8468
www.vigil.aero - candace@vigil.aero

Distribution of this Emergency Product Service Bulletin shall include, but is not limited to:

- All owners of Vigil Cutter with DEC 07 production date via our dealers.
- All AAD dealers.
- Parachute Industry Association.
- All identified parachuting publications.
- All identified parachuting Federations and Associations
- All National Aero Clubs, Parachuting Section.
- IPC Technical Committee.