



## Mars M2 Information Bulletin

Amendment to Maintenance Section 7.4 Yearly Inspection of the Mars M2 Manual.

Riggers and Advanced Packers can EITHER check the Lock Release Mechanism OR the Barometric pressure test as per the manual; but this must be completed at the manufacturers recommended time scale.

The remaining inspection procedure remains the same.

Jevicko, February 6<sup>th</sup>, 2017

  
Vratislav Malý  
MarS a.s.

