



U.S. Department  
of Transportation  
**Federal Aviation  
Administration**

Small Airplane Directorate  
1669 Phoenix Parkway, Suite 210C  
Atlanta Aircraft Certification Office  
Atlanta, GA 30349

OCT 6 1993

Mr. John B. Sherman  
Parachute Engineer  
Parachute Laboratories, Inc.  
d.b.a. Jump Shack  
1665 N. Lexington Avenue #106  
Deland, FL 32724-2187

Dear Mr. Sherman:

This is in response to your September 17, 1993, request for Federal Aviation Administration authorization to identify Part Number (P/N) SSE001 (dual harness, dual parachute pack) tandem parachute harness/container system, in accordance with the requirements of Federal Aviation Regulation (FAR) Part 21, Subpart O, Technical Standard Order (TSO) C23c, and SAE Aeronautical Standard AS-8015A, Category B.

We find your September 17, 1993, Statement of Conformance submitted with your request and your Quality Control Manual, Revision 2, dated November 3, 1990, acceptable.

The following data as submitted by your letter will be retained on file for this authorization:

a. Parachute Laboratories, Inc., d.b.a. Jump Shack Qualification Test Report, Revision B, submitted with your September 17, 1993, application.

b. Parachute Laboratories, Inc., d.b.a. Jump Shack Drawing No. SSE029, dated May 4, 1993, submitted with your September 17, 1993, application for the tandem parachute harness/container system.

All other technical data required for this authorization has been submitted for previous authorizations. This data is maintained in the applicable authorization files and has been reviewed and applied to this authorization.

Effective this date, you are authorized to identify the P/N SSE001, tandem parachute harness/container system, with the appropriate TSO markings required by the applicable TSO and FAR 21.607(d).

Additionally, the exemption from CFR 14, Subpart 105.43(a), single harness, dual parachute pack, granted to Jump Shack in 1991, is still applicable.

This authorization is not transferable to another person or location and is effective until surrendered, withdrawn, or otherwise terminated by the Administrator.

Your responsibilities as a holder of a TSO authorization are outlined in FAR 21.3 and FAR 21, Subpart O.

The Airframe Engineer for this authorization is Cindy Lorenzen, telephone number (404) 991-2910. The Technical Support Specialist is Lorraine Bush, telephone (404) 991-6137.

Sincerely,



FOR Donald T. Buckley  
Manager, Airframe Branch